



U.S. Department
of Transportation
**Federal Aviation
Administration**

North Texas Flight Standards District
Office
8700 Freeport Parkway, Suite 225
Irving, TX 75063
214-277-8513 FAX 214-277-8570

June 1, 2016

Mr. Jeff Stubbs
Accountable Manager
REB Technologies, Inc.
1500 Brown Trail
Bedford, TX 76002

Dear Mr. Stubbs:

On June 1, 2016, the North Texas Flight Standards District Office (FSDO) conducted a review of your Repair Station Capabilities List Manual, Document Number: CCL001, Revision C, and has no objection to your Repair Station utilizing this document.

Please feel free to contact me for questions regarding this inspection at 214-277-8565, or at daniel.montie@faa.gov.

Sincerely,

A handwritten signature in blue ink that reads "Daniel S. Montie".

Daniel S. Montie
Principal Avionics Inspector